- Of S-4. Connect the other end to terminal 2 of S-4.
- ⊡ Cut a 11/4" piece of the small bare wire. Place a 3/4" piece of small tubing over the wire. Solder one end to terminal 2 of S-4 (2 wires). Solder the other end to terminal 4 of S-4.
- Orange wire from the cutout in the chassis. Solder the free end to terminal 1 of S-4 (2 wires).
- White wire from the cutout in the chassis. Solder the free end to terminal 3 of S-4
- 図 Green wire from terminal 11 of S-4. Connect the free end to terminal of the meter.
- Yellow wire from terminal 10 of S-4. Connect the free end to terminal of R-16.
- C-34, .005 μ f disc capacitor. Solder one lead to terminal 2 of R-16, (2 wires). Connect the other lead to terminal 1 of R-16.
- Red-white wire from the cutout in the chassis. Solder the free end to terminal 1 of R-16 (2 wires).
- Green-white wire from the cutout in the chassis. Solder the free end Yellow wire. Solder one end to terminal 5 of S-4. Connect the other to terminal 3 of R-16.
- C-37, .005 μ f disc capacitor. Solder one lead to terminal 1 of the meter (2 wires). Solder the other lead to terminal 2 of the meter (2 wires).

end to terminal 1 of the meter.

FINAL WIRING ON THE CHASSIS

SEE FIGURE 26

- Green wire from the grommet near S-3. Solder the free end to termi-61 3 of S-3B.
- Blue wire from the grommet near S-3. Solder the free end to terminal 4 of S-3B,
- ng.1 5 of S-3B. Violet wire from the grommet near S-3. Solder the free end to termi-
- Brown wire from the grommet near S-3. Connect the free end terminal 1 of TS-7. ಕ
- If Green wire. Solder one end to terminal 1 of TS-7 (4 wires). Connect the other end to terminal 2 of J-2.

- Red wire. Solder one end to terminal 6 of S-1B. Solder the other end to terminal 1 of S-1C (2 wires).
- '12" red-white wire. Solder one end to terminal 5 of S-1B. Solder the
- White wire, Solder one end to terminal 5 of S-1A, Solder the other end to terminal 2 of TS-6 (3 wires).
- Brown-white wire. Solder one end to terminal 6 of S-1A. Solder the other end to terminal 2 of J-L.
- \mathcal{G} Violet wire. Solder one end to terminal 7 of J-1. Solder the other end to terminal 2 of TS-8 (3 wires).
- Blue wire. Solder one end to terminal 5 of 3-2. Solder the other end to terminal 2 of TS-5 (3 wires).
- Green wire. Connect one end to terminal 2 of J-2. Solder the other end to pin 7 of V-8 (2 wires).
- Elue wire. Solder one end to terminal 2 of J-2 (3 wires). Solder the other end to pin 5 of V-2 (2 wires).
- 12 C-13, .001 pf disc capacitor. Solder one lead to pin 8 of V-2. Solder the other lead to terminal 2 of TS-9 (2 wires).
- 7.R-3/100K resistor (brown, black, yellow). Solder one lead to pin 9 V-2. Solder the other lead to terminal 3 of TS-9.
- NOTE: Coils L-4 and L-5 are identical. Z C-11, 750 $\mu\mu$ f mica capacitor. Connect one lead to pin 1 of V-1. Solder the other lead to ground lug B of V-1. (2 wires).
- ☐ L-5. Solder one lead to pin 1 of V-1 (3 wires). Connect the other lead to terminal 1 of TS-15.
- Green wire. Solder one end to terminal 1 of J-4 (4 wires). Solder the other end to terminal 1 of TS-15 (2 wires).
- L-4. Solder one lead to pin 7 of V-1 (2 wires). Connect the other lead to terminal 3 of TS-15.
- E C-59, .005 af disc capacitor. Solder lead end to terminal 3 of TS-15 (4 wires). Solder the other lead to terminal 2 of TS-15.
- C-36, .005 μ f disc capacitor. Solder one lead to terminal 2 of TS-14. (2 wires). Connect the other lead to terminal 3 of TS-14.
- NOTE: There are three diodes used in the transmitter, CR-1 and CR-2, wiring the diodes be sure to position the marked end exactly as instructed a band, a dot, several colored bands or have the end colored red. When the rectifiers are identical. CR-3 the meter rectifier is different in shape than CR-1 and CR-2. The marked ends of the diodes may be marked with
- CR-3, meter rectifier. Solder the marked end to terminal 1 of TS-14 (3 wires). Solder the other lead to terminal 3 of TS-14 (3 wires).