
ADDENDA

SCHEMATIC DIAGRAM CHANGE MODELS HA-410 & HA-460 AMATEUR TRANSCEIVERS

There has been an error in printing the schematic diagram of the power socket connections on the above mentioned units. The diagram below shows the power socket connections as it should appear. It will be noted on the corrected diagram below that pins 4 and 5 of the power socket are reversed from that shown on the original schematic diagram.



LAFAYETTE RADIO ELECTRONICS CORPORATION