
From: BMG <bgordon.lsj@gmail.com>
Sent: Friday, February 3, 2012 2:18 AM
To: J Epstein
Cc: [REDACTED]
Subject: Re:

Power steering fixed

Ran Sunday and had a oil temp alarm on engine 1 Believe it is a faulty sensor Plan to swap sensor to engine 2 to confirm FYI outside of this , this hull rode 6ft seas with no problem Will bring to LSJ for weekend

Brice

Sent from my iPhone

On Feb 2, 2012, at 8:34 PM, [REDACTED] <[REDACTED]> wrote:

> JE is asking when midnight express is going to be ready.

<?xml version="1.0" encoding="UTF-8"?>

<!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">

<plist version="1.0">

<dict>

<key>date-last-viewed</key>

<integer>0</integer>

<key>date-received</key>

<integer>1328235476</integer>

<key>flags</key>

<integer>8590195713</integer>

<key>gmail-label-ids</key>

<array>

<integer>22</integer>

<integer>2</integer>

</array>

<key>remote-id</key>

<string>204545</string>

</dict>

</plist>