

To: [REDACTED]
From: jeffrey epstein
Sent: Fri 2/4/2011 7:01:47 PM
Subject: Re: B407 update

Yes

Sorry for all the typos .Sent from my iPhone

On Feb 4, 2011, at 1:07 PM, [REDACTED] wrote:

Jeffrey,
small amount of corrosion was found on drive shaft that couples the Transmission to Engine,,
this piece has very little tolerance for surface corrosion,,
Bell has on upgraded stronger Mod for this drive shaft, \$45,000.00 which is complete
replacement of the drive shaft,,

I spoke to Bell tech support and Dave Burch the manager at Edwards maintenance facility,
most operators continue to repair their own drive shaft due to the cost of this upgrade from
Bell,,

If you agree, I told Dave to remove our shaft and send for repair, estimate cost is \$3,850.00
only, however the down time is 45 days, I told them to proceed, and expedite

is this approved?

(Ghislaine, I will schedule our Bell 407 training in N491GM once the helicopter is completed,
and return to service).

I told Edwards to have the Bell 407 completed by April 1st since the Annual inspection for S76
is due at that time,, I have S76 scheduled for annual at AAG in NY, since we will utilize our
AAG money to pay for inspection,,

thanks, Larry