

BASING DIAGRAMS

COMPONENT	HEATH PART NUMBER	MAY BE REPLACED WITH	BASE DIAGRAM (BOTTOM VIEW)
Q1	417-274	RCA 40673	
Q8, Q11	417-118	G.E. OR T.I. 2N3393	
Q9, Q10	417-201	G.E. OR T.I. X29A829	
Q12	417-116	FAIRCHILD S2091	
Q2, Q3	417-169	MOT. MPF105	
Q4, Q5	417-172	MOT. MPS6521	
Q6, Q7	417-224	MOT. MPSU05	
D1, D2	56-26	1N191	
ZD1	56-55	VR-36A	
IC1	442-4	CA3035V1	

