

Date of Issue: February 2014

Affected Publication: *MPMS Chapter 5.8—Measurement of Liquid Hydrocarbons by Ultrasonic Flow Meters*, Second Edition, November 2011

ERRATA

On page 19, replace **Figure D-2** as follows:

