

**Erratum
to
ASME B29.100-2002
Precision Power Transmission, Double-Pitch Power
Transmission, and Double-Pitch Conveyor Roller
Chains, Attachments, and Sprockets**

On page 4, para. 1.5, last paragraph, 0.0015 in./ft should read 0.015 in./ft. The correct paragraph is presented below.

Overlength tolerance is $0.001/(\text{pitch in inches})^2 + 0.015 \text{ in./ft.}$
See para. 2.3 for tolerance of chain with attachments.

THE AMERICAN SOCIETY OF MECHANICAL ENGINEERS
Three Park Avenue, New York, NY 10016-5990

January 2004



K0151E