



## Standard Practice for Measuring Shape Characteristics of Tin Mill Products<sup>1</sup>

This standard is issued under the fixed designation A987/A987M; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon ( $\epsilon$ ) indicates an editorial change since the last revision or reapproval.

### 1. Scope\*

1.1 Shape is a significant quality characteristic for tin mill products. Plate-shape is affected by mill process factors plus the temper, thickness and width of the material supplied. It is the purpose of this practice to define accurately the different plate shape characteristics and to describe the practice(s) most commonly used to measure particular characteristics.

1.2 Quantitative limits are not addressed and should be established on an individual producer and user basis, where appropriate.

1.3 The values stated in either in-pound or SI units are to be regarded as standard. Within the text, the SI units are shown in brackets. The values stated in each system must be used independently of the other. Combining values from the two systems may result in nonconformance with this specification.

1.4 *This standard does not purport to address the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and to determine the applicability of regulatory limitations prior to use.*

### 2. Referenced Documents

#### 2.1 ASTM Standards:<sup>2</sup>

A599/A599M Specification for Tin Mill Products, Electrolytic Tin-Coated, Cold-Rolled Sheet

A623 Specification for Tin Mill Products, General Requirements

A623M Specification for Tin Mill Products, General Requirements [Metric]

A624/A624M Specification for Tin Mill Products, Electrolytic Tin Plate, Single Reduced

A625/A625M Specification for Tin Mill Products, Black Plate, Single-Reduced

A626/A626M Specification for Tin Mill Products, Electrolytic Tin Plate, Double Reduced

A650/A650M Specification for Tin Mill Products, Black Plate, Double Reduced

A657/A657M Specification for Tin Mill Products, Black Plate Electrolytic Chromium-Coated, Single and Double Reduced

### 3. Classification

3.1 The substrate shall conform to all the requirements of the appropriate specifications as follows: Specifications A623, A623M, A599/A599M, A624/A624M, A625/A625M, A626/A626M, A650/A650M, and A657/A657M.

### 4. Significance and Use

4.1 The definitions and procedures for measuring shape characteristics of tin mill products are provided so that purchasers and suppliers have common measuring procedures and definitions of shape characteristics. These procedures provide definitions and measuring techniques of shape characteristics. The intention of these definitions and measuring practices is not to provide a dimensional specification for shape characteristics, but rather common procedure(s) for quantifying shape anomalies.

### 5. Interferences

5.1 Measurement of shape often has been subjective, at best. Successful measurement of various shape anomalies on quantitative terms requires recognition of several factors that can interfere with accurate measurements.

5.1.1 Flat surfaces are required. Measurement of several anomalies require laying of the sample on a flat surface. A machined flat surface is recommended. Laying a sample on a floor may introduce error due to areas on a floor that are not flat.

5.1.2 Several anomalies are measured by hanging the sheet. Hanging by holding the sample with a hand can introduce error from pressures exerted by fingers. A mechanical single device clamp to help hold these samples is recommended.

5.1.3 Stepblock gauges or tapered gauges should be checked regularly with a calibrated hand micrometer. Wear or dirt build up could affect accuracy.

<sup>1</sup> This practice is under the jurisdiction of ASTM Committee A01 on Steel, Stainless Steel and Related Alloys and is the direct responsibility of Subcommittee A01.20 on Tin Mill Products.

Current edition approved Oct. 1, 2014. Published November 2014. Originally approved in 1998. Last previous edition approved in 2009 as A987 - 09. DOI: 10.1520/A0987\_A0987M-09R14.

<sup>2</sup> For referenced ASTM standards, visit the ASTM website, [www.astm.org](http://www.astm.org), or contact ASTM Customer Service at [service@astm.org](mailto:service@astm.org). For *Annual Book of ASTM Standards* volume information, refer to the standard's Document Summary page on the ASTM website.

5.1.4 Computer-based shape measuring instruments must be clean and the sensors must be in good condition. The sheet sample must be damage free.

## 6. Apparatus

6.1 Appropriate tools to measure shape anomalies are described along with drawings (attached) as required.

6.1.1 *Flat Surfaces*— Accurate measurements of shape anomalies require a flat surface, machined flat preferred.

6.1.2 *Machined Stepblock Gauge*—See Fig. 1, typically, steps are in  $\frac{1}{16}$ -in. increments.

6.1.3 *Tapered Gauge*— See Fig. 2.

6.1.4 *Standard Ruler or Tape Measure*.

6.1.5 *Hand Micrometer*.

6.1.6 *Shape Test Jig*—Fig. 3, or other shape test jigs of appropriate design.

6.1.7 *Light-Weight Straight-Edge*.

6.1.8 *Computer-based Shape Measuring Instruments* are designed for flatness measurements on samples of cold rolled sheet products or tin mill products.

## 7. Procedure

### Definitions and Measuring Practices of Shape Anomalies

7.1 *Wavy Edge* (See Fig. 4):

7.1.1 *Definition*—A series of rolling direction edge deviations from a recognized flat surface. When a sample is placed on a recognized flat table, wavy edges will appear as undulations along the edge, having the height (*A*) and a measurable cycle (*B*). This defect can be quantified using the “*R*” unit (see Section 8) or steepness calculations.

7.1.2 *Measuring Practices*:

7.1.2.1 A sample of approximately 3 ft [0.9 m] in length by coil width is placed on a flat table. Measure the height (*A*) at the peak point of each wave from the recognized flat surface with a tapered gauge or a stepblock gauge. Also measure the cycle length (*B*) from peak to peak of each wave with a ruler or tape measure.

7.1.2.2 Measure using a computer-based shape measuring instrument or other instrument of appropriate design.

7.2 *Ridge Buckle, Quarter Buckle, Center Buckle* (see Fig. 5):

7.2.1 *Definition*—These buckles are continuous deviations from a recognized flat surface occurring usually in narrow width areas parallel to the rolling direction other than at the sheet edges.

7.2.2 *Measuring Practices*:

7.2.2.1 A sheet sample of approximately 3 ft [0.9 m] by coil width is placed on a flat table. Push material diagonally along the sample to within 4 in. [10 cm] of the selected corner and measure the vertical uplift using a tapered gauge or a stepblock gauge.

7.2.2.2 Shear through the center line of the shape anomaly and measure as an edge wave using a tapered gauge or a stepblock gauge.

7.2.2.3 Measure using a computer-based shape measuring instrument or other instrument of appropriate design.

7.3 *Full Center* (see Fig. 6):

7.3.1 *Definition*—Any overall deviation of a sheet from a recognized flat surface occurring over a major portion of the sheet width parallel to the rolling direction other than at the sheet edges.

7.3.2 *Measuring Practices*:

7.3.2.1 A sheet sample of approximately 3 ft [0.9 m] by coil width is placed on a flat table. Push material diagonally along the sample until the maximum lift occurs at the selected corner and measure the vertical uplift using a tapered gauge or a stepblock gauge, or a standard ruler.

7.3.2.2 Shear through the center line of the shape anomaly and measure as an edge wave using a tapered gauge or a stepblock gauge.


7.3.2.3 Measure using a computer-based shape measuring instrument or other instrument of appropriate design.

7.4 *Edge Lift* (see Fig. 7):

7.4.1 *Definition*—Any deviation of one sheet edge other than a wavy edge. This edge lift is parallel to the rolling direction and rises when placed on a recognized flat surface.

7.4.2 *Measuring Practice*— A sheet sample of approximately 3 ft [0.9 m] by coil width is placed on a flat table. Push material diagonally along the sheet until the maximum lift occurs at the selected edge and measure the vertical distance (*A*) with a tapered gauge, a stepblock gauge, or a standard ruler.

7.5 *Coil Set and Reverse Coil Set* (see Fig. 8):



NOTE 1—This is a stepblock gauge for all thicknesses and sizes of cut sheets.


NOTE 2—Dimensions given are approximate overall dimensions.

**FIG. 1 Shape Stepblock Gauge**




NOTE 1—This is a tapered gauge for all thicknesses and sizes of cut sheets.

**FIG. 2 Shape Tapered Gauge**



NOTE 1—To measure line bow (up or down) requires the use of a shape test jig.

**FIG. 3 Shape Test Jig**



**FIG. 4 Wavy Edge**

**7.5.1 Definition**—A bow condition or deviation in the sheet as measured from a recognized flat surface. The deviation runs parallel with the rolling direction and takes the shape of a coil. Reverse coil set reverses the shape of a coil. The degree of coil set usually is determined in a vertical, free-hanging position when held against a straight-edge. Use of the shape test jig (Fig. 3) is highly recommended for this measurement.

**7.5.2 Measuring Practices:**

**7.5.2.1** A sheet sample of approximately 3 ft [0.9 m] by coil width should be held by a clamp or with the thumb and index finger. Hold the sample in the center of the rolling direction dimension. Hold the sample's edges against a recognized

straight edge, and measure the deviation (A) from the edge to the center of the sample. Use a rule accurate to  $\frac{1}{16}$  in. [or 1 mm].

**7.5.2.2** Measure the edge rise (A) of the sheet laying on a recognized flat surface.

**7.6 Twist (see Fig. 9):**

**7.6.1 Definition**—A combination of shape anomalies that results in a twisting of the sheet where diagonal corners will bow in opposite directions when the sheet is held in a vertical, free-hanging position.

**7.6.2 Measuring Practices:**




FIG. 5 Ridge Buckle, Quarter Buckle, Center Buckle




FIG. 6 Full Center




FIG. 7 Edge Lift

7.6.2.1 A sheet sample of approximately 3 ft [0.9 m] by coil width should be placed on a flat table. Measure the edge lift (A) on one side then turn the sheet over and measure the edge lift on the other side of the sample. Measure using a tapered gauge or a stepblock gauge.

7.6.2.2 A sheet sample of approximately 3 ft [0.9 m] by coil width should be held by a clamp or with the thumb and index finger in the center of the rolling direction dimension. Measure the amount of the twist by the deviation of one of the corners from a flat surface using a ruler. Flip the sample 180° and measure the deviation from vertical of the other corner, using a ruler.

7.7 Crossbow (see Fig. 10):

7.7.1 *Definition*—An edge deviation in the sheet running perpendicular to the rolling direction. Both rolling direction edges are raised measurable amounts (A) from a recognized flat surface. The degree of cross bow usually is determined in a vertical, free-hanging position held against a straight edge. Use of the shape test jig (Fig. 3) is highly recommended for this measurement.

7.7.2 *Measuring Practices:*

7.7.2.1 A sheet sample of approximately 3 ft [0.9 m] by coil width should be held by a clamp or with the thumb and the index finger in the center of sheet dimension that is perpendicular to the rolling direction. In case of dispute, a clamp no more than 2 in. [50.8 mm] wide shall be used to hold the test




FIG. 8 Coil Set and Reverse Coil Set




FIG. 9 Twist

sample. Hold the sample's edges against a recognized straight edge, and measure the deviation (A) from the straight edge to center of the sample. Use a rule accurate to  $\frac{1}{16}$  in. [or 1 mm].

7.7.2.2 Measure the edge rise of a sheet lying on a flat surface.

#### 7.8 Camber (see Fig. 11):

7.8.1 *Definition*—The greatest deviation of a coil edge from a straight line. The measurement is taken on the concave side and is the perpendicular distance from a straight line to the point of maximum deviation (A).

#### 7.8.2 *Measuring Practice*:

7.8.2.1 A sample of at least 20 ft [6 m] is laid next to an accurate straight edge. The perpendicular distance (A) is measured using a ruler accurate to  $\frac{1}{16}$  in. [or 1 mm].

7.8.2.2 *Alternate Practice of Measurement—Macro Analysis*—Cut two 20-ft [6-m] consecutive sections from master coil. Butt together the sections with similar edges. At a 10-ft [3-m] distance from the end, measure the distance between the two edges. Divide this measurement in half to determine the actual camber.

7.8.2.3 *Alternate Practice of Measurement—Micro Analysis*—Obtain consecutive customer sheared sheets equivalent to 20 ft [6 m]. Using a squaring table with a sliding gauge set at zero, slide the gauges right to left along one slit edge. The reading on the extreme left slit edge of Sheet No. 1 will be the beginning reading on the extreme right edge of Sheet No. 2. This procedure should be used from consecutive sheet to




FIG. 10 Crossbow




FIG. 11 Camber

consecutive sheet until 20 ft [6 m] have been measured. Divide the final measurement in half to determine the actual camber.

#### 7.9 Lateral Weave (see Fig. 12):

7.9.1 *Definition*—Weave is defined as oscillation of the coil or sheet edge from a straight line. The measurement is taken on the concave side and is the perpendicular distance from a straight line to the point of maximum deviation (A).

#### 7.9.2 *Measuring Practices*:

7.9.2.1 *Macro Analysis*— A sheet sample of at least 20 ft [6 m] in length is laid next to an accurate straight edge. The perpendicular distance (A) is measured using a ruler accurate to  $\frac{1}{16}$  in. [or 1 mm].

7.9.2.2 *Micro Analysis*— Obtain consecutive customer sheared sheets equivalent to 20 ft [6 m]. Using a squaring table with a sliding gauge set at zero, slide to gauges right to left along one slit edge. The reading on the extreme left slit edge of




FIG. 12 Lateral Weave



Sheet No. 1 will be the beginning reading on the extreme right edge of Sheet No. 2. This procedure should be used from consecutive sheet to consecutive sheet until 20 ft [6 m] have been measured. The individual measurements then are plotted, the maximum value being the maximum weave deviation.

## **8. I-Unit Calculation**

8.1 This calculation assumes that shape irregularities most closely conform to sinusoidal wave forms and uses the shape wave length and height for the calculation. An alternate approach is to use % steepness as a measure of the severity of shape imperfections (see [Fig. 13](#)).

## **9. Precision and Bias**


9.1 *Precision*—Precision is not specified in these measuring practices. The procedures are provided so that purchasers and suppliers have common methodology and definitions of shape characteristics.

9.2 *Bias*—Since there is no accepted reference material suitable for determining the bias of the procedures in this practice, bias has not been determined.

## **10. Keywords**

10.1 coated steel sheet; shape characteristics; tin mill products; tinplate





$F$  = Flatness Index =

$$F = KS^2$$

The difference in length between perfect flatness and a sine wave.

$K$  = wave form constant which assumes sine wave shape

$$K = \pi^2/4 = 2.47$$

$S$  = Steepness

$$S = A/B$$

$A$  = wave height

$B$  = wave length

$$F = 2.47 (A/B)^2$$

$$I \text{ Units} = 2.47 S^2 \times 10^5$$

$$\% \text{ Steepness} = A/B \times 100$$

FIG. 13 I-Unit Calculation

## SUMMARY OF CHANGES

Committee A01 has identified the location of selected changes to this standard since the last issue (A987 - 07) that may impact the use of this standard. (May 1, 2009)

(1) Added 1.3.

(2) Revised 7.3.2.1 and 7.4.2.

*ASTM International takes no position respecting the validity of any patent rights asserted in connection with any item mentioned in this standard. Users of this standard are expressly advised that determination of the validity of any such patent rights, and the risk of infringement of such rights, are entirely their own responsibility.*

*This standard is subject to revision at any time by the responsible technical committee and must be reviewed every five years and if not revised, either reapproved or withdrawn. Your comments are invited either for revision of this standard or for additional standards and should be addressed to ASTM International Headquarters. Your comments will receive careful consideration at a meeting of the responsible technical committee, which you may attend. If you feel that your comments have not received a fair hearing you should make your views known to the ASTM Committee on Standards, at the address shown below.*

*This standard is copyrighted by ASTM International, 100 Barr Harbor Drive, PO Box C700, West Conshohocken, PA 19428-2959, United States. Individual reprints (single or multiple copies) of this standard may be obtained by contacting ASTM at the above address or at 610-832-9585 (phone), 610-832-9555 (fax), or service@astm.org (e-mail); or through the ASTM website (www.astm.org). Permission rights to photocopy the standard may also be secured from the Copyright Clearance Center, 222 Rosewood Drive, Danvers, MA 01923, Tel: (978) 646-2600; http://www.copyright.com/*