
From: Larry Visoski [REDACTED]
Sent: Wednesday, July 6, 2016 2:46 AM
To: Je vacation
Subject: Update
Attachments: IMG_6232.JPG; Untitled attachment 00671.txt; IMG_6233.JPG; Untitled attachment 00674.txt

Jeffrey

Pete thought our leak was from inlet to Precooler,,blowing air fwd,

So when I returned for SJU tonight, I put a piece of tape on the suspected a=ea,, after 2 seconds I could see the tape blow up from air pressure and the= air pushed the tape away,, I'm 100% this is the gap problem we need repaired!
I just wanted to double check, I thought it was a primitive way to trouble s=oot, but accuracy counts

Before