

To: [redacted]
Cc: [redacted];
From: [redacted]
Sent: Thur 5/26/2011 5:21:06 PM
Subject: B727 interior upgrades

Jeffrey,
do you wish to proceed with cockpit seats and shower floor in Boeing at this time: quote is below:

Boeing interior

Planeperfect interior shop did not recommend Lon coin rubber floor in cockpit, it is tough to get the lon coin material to lay flat due to the seat tracks, they recommend a dark color carpet, I'll get samples for you, if you decide elect carpet in cockpit,.

BOEING

Tail # N908JE

Cockpit Proposal

cockpit seats \$7,700.00

cockpit carpet \$4,550.00

paint shower floor \$1,200.00 to match carpet

total \$13,450.00

is this apporved?

OPTION 1: Cockpit seats With New Foam \$11,790.00

OPTION 2: Without New Foam \$7,700.00 (foam is fine in our seats) I would not change foam.

The existing 4 cockpit seats will be stripped of all existing dress covers. New dress covers will be fabricated using new customer supplied leather. The existing design and pattern (including stitching) will be retained as is.

The existing cockpit seat foam will be retained as is.

Cockpit seat paint will remain as existing.

Cockpit seat belts are not included in above pricing.

All materials used will be in accordance with FAA regulations.

OPTION 3: Cockpit Carpet \$4,550.00