

Jeffrey,
attached is Edwards quote on additional items Chris found during his viewing of the Bell 430,.
to summarize and includes inlet barrier filter upgrade and interior work:
-engine inlet barrier filter upgrade, \$76,272
-overhaul auto pilot servos - \$74,848.75
-new carpet \$8,500
-new leather seats pax and cockpit \$38,500
-new windshield pilots side, \$35,158
-tail rotor hanger bearings \$8,348
-tail rotor blade \$30,337
-annual \$19,710
misc items:
total firm quote: \$308,866.75 at Edwards in Fort Lauderdale,.which includes interior and carpet work,.
just FYI info,.
thx,.
Larry

From: [REDACTED]
To: lvjet@aol.com, cgray@rotorcraftsolutions.com
CC: [REDACTED]
Sent: 2/6/2012 11:31:48 A.M. Eastern Standard Time
Subj: RE: Bell 430 s/n; 49078