

To: jeevacation@gmail.com[jeevacation@gmail.com]; Jeffrey Epstein[jeevacation@gmail.com]
From: TOM MELNICK
Sent: Thur 3/22/2012 6:01:41 PM
Subject: Re:

yes ...thin concrete has a tendency to crackcoordinating with Brian for for dock skirt.....been raining every day lately will do more harm than good if i mess with the berm... service road from flagpole down to beach ..yes this connection could use a small concrete ramp tie in section , will place this on Friday between rain showersHave you looked at the grotto pavilion layout ?? would like to start forms on Friday pour Monday...going to start steps on Monday also....poured last large section of terrace deck today ...moving quick despite the daily rain...

On Wed, Mar 21, 2012 at 4:07 PM, Jeffrey Epstein <jeevacation@gmail.com> wrote:

has the sundial started to crack,, ? dock skirt brian? , berm tops looks as it needs to be leveled behind dumpsters. the service road for my vehicle only down from the flagpole should get a pad of sombrero buff to but into the road,, any quesitons please call tomorrow

--

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of

Jeffrey Epstein

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved