

To: jeevacation@gmail.com[jeevacation@gmail.com]; J Epstein[jeevacation@gmail.com]
Cc: Sarah Kensington [REDACTED]
From: BMG
Sent: Fri 2/3/2012 2:18:20 AM
Subject: Re:

Power steering fixed
Ran Sunday and had a oil temp alarm on engine 1
Believe it is a faulty sensor
Plan to swap sensor to engine 2 to confirm
FYI outside of this , this hull rode 6ft seas with no problem Will bring to LSJ
for weekend