

Fig. 1-A. Cable stripped and prepared to receive auto radio antenna plug.




Fig. 1-B. Cable inserted in auto radio antenna plug.

The coaxial cable from the output of the converter to the receiver can be up to a maximum of about 3 feet. If some undesirable IF signals are getting through, the chances are that it is due to the long ground wire (at the antenna terminal strip) inside most receivers. A short jumper wire (1 or 2 inches) between the converter chassis and the receiver chassis will usually correct this.