




FIG. 3. SCHEMATIC DIAGRAM

THE MANUFACTURER OF THE RECEIVER THE EFFECT OF VARIOUS VARIATIONS MAY BE FOUND. IT IS RECOMMENDED THAT THE VALUE OF ANY REPLACEMENT COMPONENTS BE OBTAINED TO INSURE PROPER OPERATION IN ALL CASES.