
From: BMG <[REDACTED]>
Sent: Wednesday, February 8, 2012 7:59 PM
To: J Epstein
Cc: Larry Visoski
Subject: Midnight / twilight
Attachments: photo 1.JPG; Untitled attachment 00082.txt; photo 2.JPG; Untitled attachment 00085.txt

Retaining ring failed on port engine steering/ engine mount This was part of the intial repair As you can see engine has to be pulled to access this Parts ordered should splash Friday night All alarm codes have been cleared