

To: bellaklein [REDACTED]
Cc: [REDACTED]
From: Jeffrey Epstein
Sent: Sat 12/22/2012 12:07:52 AM
Subject: Re: Paris apt Turkish bath

ok

On Fri, Dec 21, 2012 at 4:17 PM, bellaklein <[REDACTED]> wrote:

1. Jeffrey, Valdson have a technician looking at the fact that the **steam pressure** in the turkish baths next to the massage room is not sufficient. The technician verified the system and says that with the existing installation, the pressure cannot be increased. The only possibility according to him, could be (but he was not sure) to replace the system by new machinery. I understand that Valdson informed [REDACTED] about this.

2. In the same bathroom, Valdson found that the **water pressure** in the shower is not sufficient either. He asked the technician to have a look at it. The technician explained that the water pump needs to be replaced. Valdson received the quote for repair. The cost of the pump is 1218.72 Euros (cost of the pump-731 , labor - 288 , tax -199.72) Please confirm it is approved to repair the water pump.

Thank you,
Bella

--

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of Jeffrey Epstein

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved