

To: [REDACTED]
From: Jeffrey Epstein
Sent: Sun 12/9/2012 12:28:34 AM
Subject: Re: GII autopilot

ok

On Sat, Dec 8, 2012 at 7:27 PM, <[REDACTED]> wrote:

Jeffrey,

[REDACTED] and I completed test flight on GII, during climb and Cruise flight the autopilot was smoothest I've experienced, Changing the Pitch computer repaired the Pitch surging, pourposing.

During decent the aileron had faint left/right wing rocking,.not as pronounced dutch roll we where experiencing, Roll computer is seperate unit which is suspect causing this issue,.

Meridian will exchange the roll computer,, no test flight required since its only during decent, in my opinion roll computer will remidy and we'll be good.

Thx

Larry

Sent via BlackBerry by AT&T

--

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of Jeffrey Epstein

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved