

To: Larry Viskoski [REDACTED]
From: Jeffrey Epstein
Sent: Thur 1/9/2014 2:32:12 AM
Subject: Re: GIV isolation mounts

are you sure they were changed?

On Wed, Jan 8, 2014 at 12:03 PM, Larry Viskoski [REDACTED] wrote:

Jeffrey
Photo taken from Gulfstream parts book, engine mount assembly,
Isolation mounts are the donut shape piece that floats engine at the attach point to engine frame.
These are inspected and changed during engine overhaul , last complied in 2007

Sent from my iPhone

--

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of Jeffrey Epstein

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved