

To: jeevacation@gmail.com[jeevacation@gmail.com]; jeffrey epstein[jeevacation@gmail.com]
From: BMG
Sent: Tue 4/24/2012 5:00:53 PM
Subject: Re: LSJ Five Palms Building

Ok

Do you understand the finish and the look
Also think there should be a over top rail
To finish it

Sent from my iPhone

On Apr 24, 2012, at 12:40 PM, jeffrey epstein <jeevacation@gmail.com> wrote:

They should not open further then the door opening . This drawing shows too wide

Sent from my iPad

On Apr 24, 2012, at 11:55 AM, brice gordon <[REDACTED]> wrote:

attached drawings for hangar type storm doors for your review

----- Forwarded message -----

From: <[REDACTED]>
Date: Mon, Apr 23, 2012 at 3:46 PM
Subject: LSJ Five Palms Building
To: [REDACTED]
Cc: Bob Vanbever <[REDACTED]>

PLEASE REVISE ATTACHED DRAWING FOR FIVE PALMS BUILDING
EXRIOR DOORS.

BOBBY

--

Brice Gordon
Little Saint James
USVI
Phone: [REDACTED]

<CWPR-ST JAMES DIAMOND PLATE D1-A.pdf>