

To: jeevacation@gmail.com[jeevacation@gmail.com];
jeevacation@gmail.com[jeevacation@gmail.com]
From: Lvjet
Sent: Mon 10/24/2011 1:53:35 AM
Subject: Gulfstream ready

Jeffrey,

The gulfstream has been repaired,.turned out to be mud dobber or mud wasp in static system, not visible to the eye,. originally Pete at Meridian thought it was ADC computer (Air Data Computer), Meridian parts dept was trying to locate ADC for GII, I wanted to share the parts dept comments on locating parts, which are becoming hard to find,. aircraft was built in 1974, FYI,. below are comments from parts person at Meridean.

Hi guys, I tried all the local spots with no luck. Gulfstream hasn't sold one in years (ADC). Honeywell no longer exchanges. Honeywell hasn't sold in two years. I found one in Florida. Repaired 2009 tag. I can get it counter to counter for tonight or I can get it Fedex for Monday, but for Fedex I need to know like right now or it will be too late. 3500.00 your cost. Please advise asap.